ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
10

Ward Name
Dodda Bommasandra

Street ID
W0330, W0240, W0285, W0289, W0407, W0334, W0242, W

Street Name
NA, Chikkanna Lyt, Mani Lyt 2nd Main Rd, R H B Colcny, 5th Crs

Significant Landmark
Apoorva Appartments and Sourrounding Roads

Segment No.
10/C-W0330/S085211

Total Length (m)
350.12

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	27.51	77.560005	13.061241	77.560255	13.061200	W0289	DEAD END
2	51.13	77.559950	13.060981	77.560419	13.060932	W0289	I0295
3	36.31	77.559917	13.060709	77.560249	13.060667	W0289	DEAD END
4	29.97	77.559537	13.060471	77.559812	13.060448	W0289	DEAD END
5	49.48	77.559383	13.060275	77.559418	13.060721	W0330	DEAD END
6	97.33	77.558908	13.060286	77.559795	13.060288	W0289	M0007
7	58.39	77.559218	13.059983	77.559756	13.060001	W0289	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work
Improvements to Roads Drain near Apoorva Appartments and Sourrounding Roads in ward no 10 Doddabommasandra Vidyaranayapura Sub-Division Yelahanka zo

Sanctioned Estimated Amount (Rs.)
3000000

Sanctioned Year
2015

Year
2015 - 2016

Type of Work
Asphalting

Other Work Type

Tender
Tender

Work Details
Improvements to Roads Drain near Apoorva Appartments and Sourrounding Roads in ward no 10 Doddabommasandra Vidyaranayapura Sub-Division Yelahanka zone

Job No. / Work Code
010-16-000003

Work Order No.
EE/BTP/ BBMP/E-PMT/WO/229/2015-16

Work Order Date
26/02/2016

Period of Extention
90 DAYS

Defect Liability Period From
26/02/2016

Defect Liability Period To
25/02/2017

Multiple road involved with the same Job No/ Work Code #
Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
SHIVA KUMAR		0.00

Phone No.	E-Mail ID
9448056136	

Field Inspection Details

Number of Trees	Any Other Information	Name
0		MADHAVA RAO

Date of Inspection	Remarks
22/12/2016	COMPLETED

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 10 **Ward Name:** Dodda Bommasandra **Street ID:** W0330, W0240, W0285, W0289,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	22/12/2016	21/01/2017	COMPLETED
SE	VASU K M	22/12/2016	21/01/2017	COMPLETED
EE	YARAPPA REDDY	22/12/2016	21/01/2017	COMPLETED
AEE	SHIVAKUMAR	22/12/2016	21/01/2017	COMPLETED
AE	MADHAV RAO	22/12/2016	21/01/2017	COMPLETED
AE	MADHAV RAO	22/12/2016	21/01/2017	COMPLETED